



Tbilisi Mall paint scopes

Photo #1 – Lightbox banners to be removed, and foreheads to be repainted.




Photo #2 – Lightbox banners to be removed, and foreheads to be repainted.




Photo #3 – Lightbox banners to be removed, and foreheads to be repainted.





Photo #4 – Pockets to be repainted.



Photo #5 – Ceiling under the bridges to be repainted.



Photo #6 – Cracks to be repaired and painted.



Similar cracks to be repaired, plastered and painted.

Photo #7 – Cracks to be repaired and painted.




Photo #8 – Walls at the glass elevator entrances to be repainted (Corners to be repaired).



Photo #9 – Walls at the glass elevator entrances to be repainted (Corners to be repaired).




Photo #10 – Walls in front of the Carrefour to be repainted.



Photo #11 – Lightbox banners to be removed, placed in the Tbilisi Mall warehouse.



Photo #12 – Lightbox banner’s metal substructure fixations to be cut, holes to be filled with the gypsum board, plastered and painted.



Photo #13 – Yellow exit doors to be repainted from both sides with thermal powder coating paint.

The contractor should dismantle one yellow exit door, and check the condition of the push bars and all details attached to the yellow exit door (Under the LSG's supervision).

