

GM-1 Spare Furnace Parts Package details								
Sr. No.	Details	Inside Package Dimensions in L X W X H in mm	Outside Package Dimensions in L X W X H in mm	Qty	Package Type	Net Wt. in Kg per unit	Gross Wt in Kg	Remarks
1	Various Flexibles	1200 x 1100 x 800	1300 x 1200 x 950	1	Box	850	1000	Should be kept on top
2	Heat Shield Assly	3500 x 1100 x 800	3600 x 1200 x 950	1	Box	1800	2000	Do not put anythin on this box.
3	Pressure Bellow	750 x 450 x 530	850 x 550 x 680	3	Box	1080	1380	Should be kept on top
4	Various Hangers	720 x 630 x 730	830 x 730 x 880	1	Box	850	1000	Can be stacked
5	Pressure Ring Assly	1050 x 900 x 500	1150 x 1000 x 650	6	Box	2900	3500	Can be stacked 1+1
6	Contact Shoe Assly	800 x 800 x 1300	950 x 950 x 1500	2	Steel Crate	2800	3200	Can be stacked 1+1